


ARGON THRML 30-AC QUICK ASSEMBLY GUIDE

1. Place the thermal pads on the CPU and PMIC Chip of the RPi 5.



2. Push mounting pins to fix the Argon THRML 30 Active Cooler.

